

MICRO-OHMMETER MODELS 6240 / 6255 / 6250


Verification via a ZERO Test

When you suspect that your micro-ohmmeter is not working properly and in need of repair, there's a quick field check you can do to verify if the meter itself can measure 0-Ohms.

We recommend performing a ZERO test on the meter in the field before sending it in for repair. The ZERO test will verify the meter's operation with no leads connected.

Follow these steps:

- 1 Using a bare piece of wire, connect the meter's terminals as shown (at right):
2. Set meter to highest current (10 A) and lowest measurement range possible.
3. Press **START** to execute a test. The meter should read a very low value, close to **0 Ω**.



NOTE: There is no physical connection between **C1** and **P1**.

Successful Test Results:

6255/6250 = 0.0000 mΩ or very close to this value

6240 = < 1 μΩ

Error Indications – 6255 / 6250 on Display during ZERO Test:

Error 11 = C1 and/or C2 not properly connected or broken

Error 12 = P1 not properly connected or broken

Error 13 = P2 not properly connected or broken

Error Indications - 6240 on Display during ZERO Test:

- - - - = C1 and/or C2 not properly connected or broken

~20 μΩ = P1 not properly connected or broken

>4000 μΩ = P2 not properly connected or broken

If you have any questions, contact AEMC® Technical Support at 1-800-343-1391 x351 or email techsupport@aemc.com.

Please visit and subscribe to our YouTube™ channel for informative videos on our products and software.

www.youtube.com/user/AEMCinstruments

