

# I OO,OOO-count Graphical Multimeters MTX 328 I B MTX 3282B MTX 3283B



## Contents

	3
Introduction	
Symbols used on the instrument	
Precautions and safety measures	
Safety features	
Maintenance, metrological verification Warranty	
Cleaning	
Measurement input protection systems	
Special functions	5
Description of the instrument	
Front, keyboards (illustration)	
Rear (illustration, markings)	
Measurement terminal block (illustration, markings)	6
Front (description)	
Inputs	
Display	
Functional description	
Preparation for use	
Initial settings	14
Specific configurations of the instrument	
Initialisation of the values	
Access to main functions	
Range management Display HOLD management HOLD, REL, SURV, SPEC, MEM	
Access to secondary functions	10
MATH Function	
Favorite function	
SX-DMM Software kit (option)	
Bluetooth (on –BT version)	
Technical specifications	33
Voltage measurement	
Current measurement	
Frequency measurement	
Resistance measurement	
Continuity mode	
Test diode	
Capacitance measurement	38
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B)	38 38
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple	38 38 38
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement	38 38 38 38
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement	38 38 38 38 39
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power	38 38 38 38 39 39
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement	38 38 38 38 39 39 39
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC	38 38 38 39 39 39 39
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock Influences	38 38 38 39 39 39 39 39 39 40 40
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock	38 38 38 39 39 39 39 39 39 40 40
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock Influences	38 38 38 39 39 39 39 39 39 40 40
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock Influences Multimeter traceability, calibration	38 38 39 39 39 39 39 39 39 40 40 40
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock Influences Multimeter traceability, calibration General specifications Environmental conditions Power	38 38 38 39 39 39 39 39 39 40 40 40 41 41
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock Influences Multimeter traceability, calibration General specifications Environmental conditions Power Display	38 38 39 39 39 39 39 39 39 39 39 40 40 41 41 41
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock Influences Multimeter traceability, calibration General specifications Environmental conditions Power Display Safety	38 38 39 39 39 39 39 40 40 40 41 41 41 41
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock Influences Multimeter traceability, calibration General specifications Power Display Safety CEM	38 38 38 39 39 39 39 39 39 39 39 39 40 40 41 41 41 41 42 42
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement. Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock. Influences. Multimeter traceability, calibration. General specifications Environmental conditions Power Display Safety CEM RS232 DB9F and USB optical cables (options).	
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power Duty ratio DC+, DC Pulse counting CNT+, CNT Clock Influences Multimeter traceability, calibration General specifications Environmental conditions Power Display Safety CEM RS232 DB9F and USB optical cables (options)	38 38 38 39 39 39 39 39 39 39 40 40 41 41 41 41 41 42 42 42
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement. Positive or negative peak measurement Resistive power. Duty ratio DC+, DC Pulse counting CNT+, CNT Clock. Influences. Multimeter traceability, calibration. General specifications Environmental conditions Power Display. Safety. CEM RS232 DB9F and USB optical cables (options). Mechanical characteristics Box	38 38 38 39 39 39 39 39 39 39 39 40 41 41 41 41 41 42 42 42 42
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement Positive or negative peak measurement Resistive power. Duty ratio DC+, DC- Pulse counting CNT+, CNT- Clock Influences. Multimeter traceability, calibration. General specifications Environmental conditions Power Display Safety. CEM RS232 DB9F and USB optical cables (options). Mechanical characteristics Box Packaging	38 38 38 39 39 39 39 39 39 39 39 40 41 41 41 41 42 42 42 42 42
Capacitance measurement Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282B, MTX 3283B) Temperature measurement with J or K thermocouple dBm measurement. Positive or negative peak measurement Resistive power. Duty ratio DC+, DC Pulse counting CNT+, CNT Clock. Influences. Multimeter traceability, calibration. General specifications Environmental conditions Power Display. Safety. CEM RS232 DB9F and USB optical cables (options). Mechanical characteristics Box	38 38 38 39 39 39 39 39 39 39 39 40 41 41 41 41 42 42 42 42 42

## **General instructions**



You have just acquired a 100,000-count graphical multimeter.

Thank you for your trust in our products.

It complies with safety standard EN 61010-1 (2001), double insulation, relative to electronic measuring instruments.

For optimum service, read this MANUAL carefully and comply with the operating precautions.

Symbols used on the instrument

Warning: Risk of danger.

Refer to the operating MANUAL to find out the nature of the potential hazards and the action necessary to avoid such hazards.



Equipment protected throughout by double insulation.

The rubbish bin with a line through it means that in the European Union, the product must undergo selective disposal for the recycling of electric and electronic material, in compliance with Directive WEEE 2002/96/EC.



Attention : Risk of electrical shock

# Precautions and safety measures

- Read carefully all the notes preceded by the symbol A.
- If you use this instrument in a way which is not specified, the protection which it provides may be compromised, putting you in danger.
- The safety of any system incorporating this instrument is the responsibility of the system assembler.
- This instrument has been designed for use indoors:
  - in an environment with pollution level 2,
  - at an altitude of less than 2000 m,
  - at a temperature between 0° C and 55° C
  - with relative humidity of less than 80% up to 31° C.



- Measurement category III for voltages no higher than 1000 V (AC or DC) in relation to the earth.
  - Measurement category IV for voltages no higher than 600 V (AC or DC) in relation to the earth.

Definition of measurement categories <u>CAT III</u>: Measurement category III corresponds to measurements on building installations. <u>Example</u>: measurements on distribution panels, cabling, etc.

<u>CAT IV</u> : Measurement category IV corresponds to measurements taken at the source of lowvoltage installations Example: metering and measurements on overvoltage protection devices...

**before use** • Comply with environmental and storage conditions.

- For your safety, only use the leads delivered with the instrument: they comply with the norm EN 61010-1 (2001).
- Before using it, systematically check that it is in perfect condition.

during use 🤞

- As a safety measure, use only suitable leads and accessories supplied with the instrument or approved by the manufacturer.
- If the measurement category of the accessory is different from that of the apparatus, the lowest category applies to the unit.
- Never exceed the protection limit values indicated in the specifications for each type of measurement.
- Before changing the function, disconnect the measurement leads from the circuit measured.
- Never measure resistances on a live circuit.
- When the instrument is connected to the measurement circuits, never touch an unused terminal.

## General instructions (cont'd)

Safety features	
-----------------	--

- It is impossible to access the battery or fuse compartment without first disconnecting the measurement leads.
- When measuring voltages greater than 60 VDC or 30 VAC, the A symbol flashes on the display.
- Automatic detection of a connection on the "Ampere" terminal.
- When there is a persistent range overrun, an intermittent buzzer indicates the risk of electric shock.

# Maintenance and metrological verification

Any access to the internal circuits for adjustment, servicing or repair of the unit *under power* must be undertaken only by qualified personnel, after reading the instructions in this MANUAL.



A **qualified person** is a person who is familiar with the installation, its construction, its use and the hazards that exist. They are authorized to activate and deactivate the installation and equipment, in compliance with the safety instructions.

For all repairs under or outside of the warranty, return the device to your retailer.

#### Warranty

workmanship, in accordance with the general terms and conditions of sale. During this period, the equipment can only be repaired by the manufacturer. The

This equipment is guaranteed for **3 years** against any defect in materials or



During this period, the equipment can only be repaired by the manufacturer. The manufacturer reserves the right to carry out repair or replacement of all or part of the equipment.

If the equipment is returned to the manufacturer, initial transport costs shall be borne by the customer.

The warranty does not apply in the event of:

- unsuitable use of the equipment or use with other incompatible equipment
- modification of the equipment without explicit authorization from the manufacturer's technical services
- · repair carried out by a person not certified by the manufacturer
- adaptation to a specific application, not provided for in the definition of the equipment or by the operating MANUAL
- an impact, a fall or flooding.

# Unpacking - repacking



All the equipment was verified mechanically and electrically before shipping.

When you receive it, carry out a quick check to detect any damage that may have occurred during transport. If necessary, contact our sales department immediately and register any legal reservations with the carrier.

In the event of reshipping, it is preferable to use the original package. Indicate the reasons for the return as clearly as possible in a note attached to the equipment.

#### Cleaning



- Turn the instrument off.
- Clean it with a damp cloth and soap.
- Never use abrasive products or solvents.
- Allow to dry before any further use.

## General instructions (cont'd)

# Measurement input protection systems

These multimeters are equipped with several protection systems:

- Varistor protection clips any transient overvoltages on the measurement terminals.
- PTC (positive temperature coefficient) protection protects against permanent overvoltages less than or equal to 1000 V during capacitance or resistance measurements and diode tests. This protection is reset automatically after the overload.
- A fuse (11 A) provides protection during intensity measurements.

#### Special functions

Automatic current measurement detection The number of input terminals is limited to 3: **V**, **COM**, **A**. Connection of the lead to the "**A**mpere" terminal automatically selects the corresponding function.

#### When a function modification by the control keyboard is incompatible with the lead connection, it triggers a buzzer and a visual alarm (LEADS).

The current measurement is performed using autorange over the whole range.

#### Auto power-off



If the function is validated in the Sleep menu: the instrument shuts down automatically after 30 minutes if no action has occurred on the front panel during that time.

The instrument can be powered up again by pressing the O key.

Automatic power-off is inhibited in:

- Surveillance mode (SURV)
- Memorize mode (MEM)
- Communication mode (CC) (optical link RS232C, USB, Bluetooth)
- when the value measured (Voltage or Current) on the multimeter's inputs exceeds the danger level.

#### Alert signal

An intermittent buzzer sounds:



- on the "Voltage" position, when the range is exceeded (MANUAL and AUTO mode last range)
- on the "Current" position, when the range is exceeded (MANUAL) mode, when 10 Amperes or more is measured
- if the position of the leads and the function selected are incompatible
- when the danger thresholds are exceeded (function activated)

When the range is exceeded, the buzzer is accompanied by display of "O. L".


**Danger threshold** 

When this symbol is activated:



- the voltage on the "Volt" input exceeds 60 VDC or 30 VAC
- the current injected between the "Ampere" and COM exceeds 10 A
- the range is exceeded (voltage or current) in MANUAL mode

# **Description of the instrument**



## Description of the instrument (cont'd)

#### Front (description)

1 power on/off key

- Starting the multimeter.
- Stopping the multimeter.
  - If there is a multimeter malfunction, a long press (> 1 s) on this key can be used to return to normal operation.

#### 8 keys for selecting the main functions

Voltage measurement or access to the measurement type: AC, DC or AC+DC

- Selection using this key or the LUL keys.
- Validation using the W key or after 2 s.



Current measurement or access to the measurement type: AC, DC or AC+DC

- Selection using this key or the **U**
- Validation using the W key or after 2 s.



Measurement of **Frequency** (Hz) on a VAC voltage or access to the MANUAL frequency range < 900 kHz (default) or > 900 kHz.

A long press opens the menu for changing the voltage range.

- Selection using the LLL keys.
- Validation using the 🖤 or 🖉 keys.
- 🖞 Voltage range quick change using the 🛄 keys.

The selected range is recalled in the help line (i), see page 9.



Measurement of Resistance (Ohm)

By pressing again:

- Access to the **Continuity** test (♪)
- Access to Diode test (➔)

Measurement of **Temperature** or access to the types of temperature measurements: ° C, ° F or K.

- Selection using the LLL keys.
- Validation using the W key or after 2 s.
- By pressing this key during measurement type selection, you can access the sensor type:
  - platinum probes: Pt 100, Pt 1000 only on MTX 3282B and MTX 3283B
  - thermocouples: J (TC J), K (TC K)
- Selection using the www keys.
- Validation using the W key or after 2 s.

The selected scale is recalled in the help line (i), see page 9.



Measurement of Capacitance

"Favorite" measurement configurable by the user.

A long press opens the "favorite" function configuration menu.

For the menu's configuration, see §. © Function.

## **Description of the instrument (cont'd)**



Instrument Configuration menu.

This key can also be used to exit from a menu or submenu after validating it.

# 3 keys for navigation and modification of the menus

- Selection of a menu or function (up/down navigation).
- Increase or decrease of the variable selected.



- Selection of a function (left/right navigation).
- Modification of a function.
- Movement within sub-menus.

## 6 keys for activating the instrument's various modes

Range

#### Selection of the operating mode:

AUTO, AUTO PEAK (MTX 3282B, MTX 3283B), MANUAL.

- Selection using this key or the **IIII** keys.
- Validation using the way way or after 2 s.

If the measurement is single range, the range defined is forced and there is no effect if this key is pressed.

Se Example: Diode test, continuity test and temperature measurement.

By pressing one of the **W** keys, you can switch directly to **MANUAL** mode and then modify the range.



Activation, deactivation of the **REL** (relative) mode. When it is active, a long press opens a window for setting the reference.



Activation, deactivation of the display of the **specifications** for the function and range selected.

Hold

Activation of HOLD or AUTO HOLD mode, deactivation NO HOLD.

- Selection using this key or the **W** keys.
- Validation using the W key or after 2 s.



Activation, deactivation of the **SURV** (surveillance) mode. A long press opens a window for viewing the most recent records. Closed by a short press.

Activation, deactivation of the **MEM** (automatic recording) mode. A long press opens the **MEM Function menu.** 

#### 2 utility keys



**Back-lighting** of the display in dark environments. A long press opens the menu for adjusting the **contrast** on the LCD.




Selection of the functions for the **3 secondary displays**.

- Selection by successive presses on this key.
- A long press can be used to exit from this mode.

## **Description of the instrument (cont'd)**

Inputs VΩ⊣⊢→⊢ A	Input for voltage and frequency measurements, diode tests, resistance measurements, continuity tests, and capacitance or temperature measurements. Input for current measurements.			
СОМ	Reference input.			
Display (foot of the screen)	<ul> <li>The multimeters in this range are equipped with a graphical LCD screen (58 mm x 58 mm) with 160 x 160 resolution for comfortable reading.</li> <li>Reading of the LCD can be optimized by varying the orientation of the display, the adjustment of contrast and, if necessary, using the backlighting</li> <li>The modes, the functions selected, the electrical or physical values measured and the alert symbols are clearly shown on the display.</li> <li>The user can call up help (i) regarding the function selected.</li> <li>The main display is accompanied by its sign and the unit.</li> </ul>			
	Depending on the current selections, the display may be graphical or digital:			
Graphical display	The graphical window can be used to monitor the evolution of the principal measurement.         Example         Auto			

The graphical window and the bargraph constantly track the evolution of the measurement in the range selected.



10

-

ν


Secondary display 1

Secondary display 2

Secondary display 3

Lower status line

Help on function



SURV

**Recording started** 

MEM

-10

i

MIN

MAX

AVG

The main display and the bargraph constantly track the evolution of the measurement.

## **Functional description**

Preparation for use				
Instructions before activation	To use this instrument, you must comply with the usual safety rules in order - to protect you against the dangers of the electric current, - to protect the multimeter against incorrect operations. For your safety, only use the leads delivered with the instrument. Before using it, systematically check that it is in perfect condition.			
Instrument power supply	<ul> <li>The 3 multimeters in this range operate with three 1.5 V alkaline batteries (LR6-AM3 AA) or three 1.2 V Ni-MH rechargeable batteries (accumulators) of the same type:</li> </ul>			
	The MTX 3281B is delivered with three 1.5 V alkaline batteries (LR6-AM3 AA). It can operate with accumulators, but does not allow in situ recharging (see §. Accessories delivered as options).			
	The MTX 3282B and MTX 3283B multimeters are delivered with three 1.2			
	V Ni-MH accumulators and charger (12 VDC 7.2 VA) for AC power operation while simultaneously charging the batteries.			
	<ul> <li>When the charger is connected directly to the instrument, the accumulators can be recharged without removing them from the multimeter.</li> </ul>			
	• The multimeter can only operate if the accu./batteries are in place.			
Power on 🔘	Using the key opposite.			
Charge indicator	A charge status indicator for the batteries or accumulators is constantly shown on the display:			
	<b>ETTER</b> : Batteries or accumulators > 75 % charged			
	Batteries or accumulators > 25 % charged			
	i minimum charge level < 25 %			
	The symbol flashes on the display and a buzzer sounds if the power voltage is insufficient (only 30 min charge life). As the specifications will no longer be guaranteed, you must then replace the batteries or recharge the accumulators (see next page).			
8	There can be differences between the display of the charge level (symbol) and the real charge level of the accumulators, according to the quality and the performances of those.			
	To avoid this risk, we recommend to use the same accumulators (HX0051) as those delivered by the manufacturer (see p. 43).			

When getting started, the apparatus needs a few seconds to display a correct level of charge (symbol).

#### Selection of energy type

For correct management of the battery or accumulator charge status indicator, the type of power must be selected:

- Opening of the **Configuration** menu with the *w* key.
- Selection of the "General" function using the LIII keys.
- Validation of General settings using the Wey.

Configuration	
General	•
Measure	•
Func. 🙂	<b>•</b>
Func. MATH	•
General settin	gs 🔹

• Selection of **Energy Type** menu using the **U** keys.

General	•
IR baud	9600
Config	user
Energy	bat.
Accumulate	or 🖶
Energy type	

- Modification of the Energy Type (battery or acc.) using the Wey.
- Validation and exit from the successive menus using the *w* key.

Recharging the Befor accumulators instru

Before carrying out this operation, check that the accumulators are fitted in the instrument ; they do not need to be removed from the multimeter to be recharged.

Recharging is only possible if "Accumulator" has been selected in the Energy Type menu (see above).




If you try to recharge the accumulators when the batteries are fitted in the multimeter, it could damage it.

For safety reasons, the accumulators should only be loaded at between 0 and 40  $^{\circ}\text{C}.$ 

Caution High internal temperature due to a current measurement may trigger the thermal security mechanism.

Recharging the accumulators (cont'd)

- Before carrying out this operation, select the capacity of the accumulators (2600 mAh by default) fitted in the instrument:
- Selection: Accumulator in the using the **W** keys.
- Validation: Accumulator using the wkey, opens a menu for setting the accumulator capacity (in mAh):



- Selection of the digit to be modified using the W key.
- Modification of the value using the **U**
- Validation of the accumulator capacity and exit from the successive menus using the key

To maintain the accumulators in good condition, run the accumulators down to the minimum charge level **\_\_\_** before recharging.

- Then connect the power pack (12 VDC, 7.2 VAC) to the jack connector (see front panel illustration).
- Connect the power pack (12 VDC, 7.2 VAC) to the AC Power supply.

ø

The symbol opposite on the display allows you to monitor the charge status.

The accumulators are fully charged when the symbol is full **EEEE**.


The **MTX 3282B** and **MTX 3283B** multimeters contain Ni-MH accumulators. These accumulators must be disposed of by a recycling firm or a company specialized in the treatment of dangerous waste materials.



#### *Never dispose of these accumulators with other solid waste. For further information, contact your AEMC dealer.*

When the multimeter is delivered, the accumulators may be discharged, requiring a complete recharge.

Recharging the accumulators with multimeter off




The **scrolling** symbol shows the progress of recharging.

Once the accumulators have been fully recharged, the instrument shuts down automatically.

Battery cha	rging
Charge level:	
75%100%	


Wall plug power unit	Use only the charger that is delivered with this device, which is a 2nd generation multimeter. The charger from the previous generation is not compatible.			
Recharging totally discharged accumulators or new batteries	<ol> <li>Fit the batteries into the multimeter, then connect the charger.</li> <li>Wait approximately 30 minutes, then press the ON button to switch on the multimeter and follow the progress of the charge. Average charging period : 7h30 (with 2600 mAh accumulators)</li> <li>After one effective hour of recharging, the multimeter can be used for measurements, by pressing again on the ON button.</li> </ol>			
"A measurement" protection fuse	A fuse provides protection up to 11 A for current measurements. It must be replaced only with an identical fuse: 11 A, 20 kA, 1000 V, 10 x 38 mm (High Interrupting Capacity).			
Checking of current measurement fuse	<ol> <li>Test the current measurement as follows:</li> <li>Select the Ampere function using the A key.</li> <li>Connect a lead to the A terminal.</li> <li>Check that the LEADS indication disappears from the display (presence of lead). If this is not the case, replace the fuse.</li> </ol>			
Replacement of the fuse or the batteries	<ul> <li>Before replacing the fuse or batteries, comply with the safety instructions given at the beginning of this MANUAL. Then:</li> <li>1. Disconnect the test leads from the measurement circuits and the instrument.</li> <li>2. Disconnect the power lead from the MTX 3282B or MTX 3283B 12 VDC power pack.</li> <li>3. Switch off the power to the instrument.</li> <li>4. Undo the screw on the back of the instrument.</li> <li>5. Pivot the rear cover of the casing to access the battery/fuse compartment.</li> <li>6. Remove the fuse or batteries and replace them with identical models.</li> <li>7. Replace the cover and retighten the screw.</li> <li>Without batteries, the date and time are kept for ca. 1 min in the instrument. The measurements recorded are kept for an unlimited time.</li> </ul>			
Dismantling of multimeter and access to battery/fuse compartment	batteries			



Initial settings

The general menu configures the parameters of the multimeter according to the conditions of use and the user's preferences.


- Opening of the Configuration menu with the *work* key.
- Selection of the **General** menu using the **III** keys and then the **v** key.



#### Choice of language

Setting the date and time

Selection of the language for the multimeter's menus. Two options are available: French (**Fr**) or English (**En**, default).



- Selection of the variables using the W key.
- Modification of the value using WU keys.
- Clock validation and start-up when menu is closed using key.

Activation of the buzzer (Beep)

Validation (default), or not , of audio signal (beep) when:

- a key is pressed,
- there is a voltage of more than 60 VDC or 30 VAC on the "V" input,
- a stable measurement is acquired in AUTO HOLD mode,
- the power supply voltage (battery) is insufficient.
- The audio signal is maintained even when the buzzer is deactivated :
  - \* during continuity testing,
  - \* when the range is exceeded (voltage or current),
  - \* on a 10 A measurement,
  - \* if the position of the leads and the function selected are incompatible.

Validation (default), or not, of automatic shutdown (**sleep**) after 30 min if there has been no action on the multimeter's front panel during that time.

In **SURV**, **MEM** and **Communication modes**, automatic shutdown is not validated.



For your safety, automatic shutdown is inhibited when the values measured (voltage, current) on the inputs exceed the danger thresholds (*indicator opposite displayed*).

Display contrast

shutdown (sleep)

Automatic

Contrast	<ul> <li>Modification of the value (default: 50 using the key.</li> <li>Validation of setting using key</li> </ul>

A long press on directly opens the menu, *with validates the setting*.

%)

Adjustment of back-lighting	Selection of the <b>back-lighting</b> deactive consumption. 6 times are possible: <b>10 s</b> , <b>30 s, 1 min,</b> deactivation).	ation time to limit the multimeter's energy <b>2 min</b> (default) <b>, 10 min</b> or <b>infinite</b> (no	
Start-up configuration	<ul> <li>In user mode, the instrument resta and the main function selected whe</li> </ul>	rts with the user's personal configuration en it was switched off.	
(Config)	<ul> <li>In basic mode, by default, the multimeter restarts with its elementary configuration and the Volt (AC+DC) function.</li> </ul>		
	Restart configuration indicated without leads connected. If the leads are connected, they will be taken into account for function selection.		
ific gurations	Using the Measure menu, you can ada measurement environment:	apt the instrument's configuration to the	
e instrument	Measure	<ul> <li>Opening of the Configuration menu</li> </ul>	
	Filter ves	with the 🦾 key.	

1G

Selection of the Measure menu using

the keys and then the wey.

Speci config of the

> Activation of a filter to improve frequency rejection for measurements in low VDC Filter mode.

> > μ By default, filter active.

Impedance

Filter activation

dBm REF W REF


Impedance

Choice of the required input impedance on the 100 and 1000 mV (1 V) ranges.

- 100 mVDC and AC+DC range: 2 possible impedances: 1 G $\Omega$  or 10  $M\Omega$
- 1000 mV mVDC range: 2 possible impedances: 1 G $\Omega$  or 20 M $\Omega$
- (C) By default, 100 mV range = 10 M $\Omega$ , 1000 mV range = 20 M $\Omega$



Adjustment of the reference resistance value (dBm REF) between 1  $\Omega$  and 10,000  $\Omega$ , for measurements in dBm on VAC or VAC+VDC voltages:



- Selection of the digit to be modified using the W key.
- Modification of the value using the WU keys.
- · Validation of the reference resistance in dBm and exit from the menu using the key.

#### ø Default value 600 Ω.

Reminder

A 0 dBm measurement with a 600  $\Omega$  reference resistance is given on a voltage of 0.7746 VAC.

<i>W REF</i> MTX 3283B	Adjustment of the reference resistance value ( <b>W REF)</b> between 1 $\Omega$ and 10,000 $\Omega$ for resistive power measurements:				
	The calculation	performed is:	(voltage me	asured) <sup>2</sup> / W REF	(unit W)
	The adjustmen	t procedure is the	•	asured) <sup>2</sup> * <b>W REI</b> r the dBm referen	
	Default va	•			ice resistance.
		used to calculate t	the resistive	power (W) with	
		EF and to calcula			(Ref) = W REF
Initialization of the values	<ul> <li>The parameters of the configuration can be reinitialized to the default settings in a single operation:</li> </ul>				
	<ul> <li>Opening of the Configuration menu with the <i>m</i> key.</li> </ul>				
	Configuration • Selection of the "Default init"				diversity official
	Func.	○ +		function using th	e 🛄 keys.
	Func.	MATH 🖶	•	Validation of initi	alization using the
	Func.	MEM 🖶		ey.	
	Defau				
	-				
	Set default values				
	Loading of t	ne default values i	s confirmed	by the following	message:
	Loading of the default values is confirmed by the following message:           Message				
	Exit from the successive menus using				
	Default values the wey.				
	loaded  The language and the function are not mode				
	function are not modified.			iodilled.	
d Default values	General	Language :	Fr	Beep :	on
V Default values		<u>Sleep</u> : Lighting :	on 2 min	Contrast : Communication	50 % : IR
		IR baud :	9600	Configuration :	basic
		Energy 3281B :	battery	Energy 3282B, 3	283B
		Accu. capacity :	2600 mAh		
	Measure	Filter :	active	Impedance :	10 / 20 M
	Favorite func.	dBm REF : Function :	600 Ω V	<u>W REF</u> : Unit :	50 Ω none
	MATH func.	<u>Coef. A</u> :	v 1	<u>Coef. B</u> :	0
	MEM func.	Recording freq. : No. of rec. 3281B rec. 3282B, 3283E	]:	158	<u>No. of</u>
	Main func.		), AC+DC AUTO	<u>Hz</u> : ° <u>C</u> :	10 V range ° C, Pt 100
			AUTO	<u>u</u> .	0,11100

#### Access to main functions

**Connection of leads** 

```
The input terminals are limited to 3 : COM, V, \Omega, \rightarrow + and A. Connect the black lead to the COM socket (for all measurements).
```

Functions authorized when connected on the V  $\Omega \rightarrow$  terminal



#### Voltage measurement (Volt).

**PEAK** is displayed when a peak (Pk+ Pk-measurement) of voltage is detected and when it is higher than the range of active voltage.





A 1st press gives access to **Resistance** measurements (Ohm).

A 2nd press gives access to **Continuity** measurements ( $\checkmark$ ).

A 3rd press gives access to **Diode** measurements (+).



A 1st press gives access to **Temperature** measurements (according to the last configuration of the function).

A 2nd press gives access to the type of temperature measurement: ° C, ° F, K.

Selection using the IIII keys, validation using the 😎 key or after 2 s.

Another press on this key while selecting the measurement type gives access to **the type of sensors**:

- platinum probes: Pt100 or Pt1000 only on MTX 3282B, MTX 3283B

- thermocouples: J or K (TC J, TC K)

Selection using the  $\blacksquare$  keys, validation using the  $\boxdot$  key or after 2 s.

When the red lead is connected to the A terminal, it automatically selects

If current measurement is selected without connection of a lead to terminal A



Measurement of Capacitance.



"Favorite" measurement configurable by the user.

I For the menu's configuration, see §. ☺ Function.



Instrument Configuration menu.

Current (AC + DC) measurement.

Functions authorized when connected to the A terminal

or without a protection fuse, the **LEADS** symbol flashes on the display. **Current** measurement (Ampere)

The current measurement may be performed using autorange (AUTO PEAK) over the whole scope of the ranges (μA, mA, A).

**PEAK** is displayed when a peak (Pk+ Pk- measurement) of current is detected and when it is higher than the range of active current.



"Favorite" measurement configurable by the user.

Instrument Configuration menu.




Range management	<ul> <li>The Range key gives access to three operating modes:</li> <li>AUTO mode</li> <li>AUTO PEAK mode MTX 3282B, MTX 3283B</li> <li>MANU mode</li> <li>Selection using this key or the Reys.</li> <li>Validation using the key or after 2 s.</li> <li>If the measurement is single range, the range defined is forced and there is no effect if the Range key is pressed.</li> <li>Example: Diode test, continuity test and temperature measurement.</li> </ul>
"AUTO" mode	On the input for a measurement, <b>AUTO</b> mode is active by default and range selection is managed automatically by the multimeter.
"AUTO PEAK" mode MTX 3282B MTX 3283B	<ul> <li>In AUTO PEAK mode, the range changes are performed on the basis of rapid acquisition of peaks, either upward or downward.</li> <li><i>AUTO PEAK mode is only accessible for AC, AC+DC in V and A measurements. It prevents untimely overruns of the peak factor specified for the instrument.</i></li> </ul>
"MANUAL" mode	<ul> <li>When this mode is selected and is valid for the function concerned, the keys can be used to modify the measurement range.</li> <li>Measurements concerned: voltage, current, resistance, capacitance.</li> <li>By pressing one of the keys, you can switch directly to MANUAL mode and then modify the range.</li> </ul>
Display hold management	<ul> <li>The Hold key gives access to two operating modes:</li> <li>HOLD mode</li> <li>AUTO HOLD mode</li> <li>NO HOLD deactivates the mode.</li> <li>Selection using this key or the keys.</li> <li>Validation using the key or after 2 s.</li> </ul>
HOLD	<ul> <li>HOLD mode freezes on the screen the current main measurement at the time when the key is pressed. The instrument continues to manage the measurements and display them in the graphical window or on the secondary display (REL mode).</li> <li>The range selection remains unchanged: AUTO or MANUAL depending on the configuration when you enter this mode.</li> </ul>
AUTO HOLD	<ul> <li>AUTO HOLD mode automatically freezes on the screen the current main measurement whenever a stable measurement is detected. It is confirmed by a beep (unless the configuration "Beep <i>no</i>" has been selected in the Configuration menu).</li> <li>The values memorized remain displayed until the next stable measurement taken (measurement different from ± 100 digits) or until deactivation of AUTO HOLD mode.</li> <li>The instrument continues to manage the measurements and display them in the graphical window or on the secondary display (REL mode).</li> <li>The range selection remains unchanged (AUTO or MANUAL) depending on the configuration when you enter this mode. AUTO HOLD mode is only accessible for V and A measurements.</li> </ul>

- **REL** mode takes the current main measurement as its reference. It is indicated on the secondary display: **REF**.
  - The main display continues to indicate the instantaneous value measured and the bargraph.
  - The secondary display ∆ indicates the absolute deviation between the instantaneous value measured and the reference recorded.
  - The secondary display  $\Delta$  % indicates the relative deviation in % between the instantaneous value measured and the reference recorded.
  - Range management may be "AUTOmatic" or "MANUAL, depending on the configuration when entering this mode.
  - $\overset{d}{=}$  The  $\varDelta$  and  $\varDelta$  % displays are managed in the same range.

In "AUTO" mode, they cannot fall below the reference range when the REL mode was activated.

Example: Measurement of a 1.5 VDC voltage with a reference set to 1 V:




# Adjustment of the reference

When the mode is active, a long press on the key opens a window for setting the **REF reference**.


- The Wey selects the digit to be modified.
- The LLL keys modify the digit selected.
- The *model* key can be used to exit from the menu after validating the new reference.

🖎 Example:



- SURV
   The SURV mode monitors the variations of a signal by recording the extreme values (MIN and MAX) of the main measurement and calculating the average (AVG). For each value memorized the multimeter records the corresponding date and time.
  - When it is started up, the MTX 3281B reinitializes the date and time (01:01:2000, 00:00). Before starting work, set the correct date and time to "date-stamp" the records see §. Setting the date and time).
  - When you enter **SURV** mode by a short press on the key, the last **MIN** and **MAX** measurements are erased and then initialized with the current measurement.
    - SURV flashes when the mode is active.
  - AVG shows the average of all the measurements recorded since SURV mode was activated.
  - The data recorded can be viewed by a long press on the surveillance or after exiting from the mode.
  - In SURV mode:
    - MANU or AUTO range management cannot be selected.
    - the current measurement, the MIN value and the MAX value are presented in the most suitable range for each of them.

🖎 Example:



Surv

SURV	
Start :	
27/03/2005	10 :07 :11
Stop :	
27/03/2005	10 :10 :30
Mini : -1.0000	
27/03/2005	10 :08 :25
Max: 2.5000	V
27/03/2005	10 :09 :25
Avg : 1.3000	V

Consultation of recorded data by a

long press on the key

The data recorded is accompanied by the date, time and surveillance range.

• Exit from consultation by a short


press on the

**SPEC** On the basis of the technical specifications, the **SPEC** mode directly displays the tolerance of the measurement in progress, so that there is no need to search for it and calculate it.

On the basis of the main measurement, the display:

- indicates the specifications (x % of reading ± n digit) according to the type of measurement, the range selected and the frequency (in AC and AC+DC)
- calculates the interval containing the true value, if the instrument is within its tolerance: SMIN value → minimum specification

SMAX value → maximum specification



In AC+DC, the specifications are calculated only if the frequency can be measured (see §. Secondary Functions) and is > 45 Hz.

- **MEM MEM** mode records the contents of the digital display(s) in the memory of the instrument at a pre-programmed rate.
  - A short press on entry starts a series of recordings.
  - The **MEM** symbol flashes throughout the recording period; it is accompanied by the number of recordings made.
  - Memorization of the measurements can be stopped by another short press.
  - The number of values to be memorized for a measurement run is programmable: it therefore stops recording automatically.
  - Another press on starts a new series of recordings.

MTX 3281B MTX 3282B, MTX 3283B	Recording capacity	158 measurements per sequence 6500 measurements maximum	1 to 10 sequences 1 to 10 sequences (depending on available memory)
Example: activation of MEM mode during surveillance mode		-1.0000 V 2.5000 V 1.3000 V	• Furthermore, the <b>MEM</b> mode may be activated during the <b>SURV</b> mode or during display of the secondary functions. The parameters set are saved. It will then be possible to select them and display them as the main function.

SURV MEM 2

(When it is started up, the MTX 3281B reinitializes the date and time (01:01:2000, 00:00:00).

Before starting work, set the correct date and time to "date-stamp" the records. See §. Setting the date and time).

#### Configuration of MEM mode

The **MEM** mode is configured in the **Func. MEM** function of the **Configuration Menu.** 


- Opening of the **Configuration** menu with the *w* key.
- Selection of the "Func. MEM" function using the Markeys.

			•	
		Measure Func. © Func. MATH	• • •	
		Func. MEM	•	
		Function MEN settings	M	
	<ul> <li>Validation of Fur</li> </ul>	ic. MEM using the	key.	
	d A long press on	Mem opens the M	IEM Function m	enu.
Programming the recording frequency	Selection of the "I	RATE" function using		1
nequency		Consult Erase Erase all	erase	
		Rate	<b>-</b>	
		Recording ra	te	
		with the every key open ours, minutes and se		etting the required
		Rate h:mn 00 : 00	:s ):02	
	<ul> <li>Modification of the</li> </ul>	variables, hour, minute value using the unique the value using the unique surement recording the value	keys.	

The minimum recording rate is 23 h, 59 min, 59 s. Default recording rate 1s.

Programming of the number of records By defining a number of records for a measurement campaign, it is possible to stop recording automatically.

- Selection of the number of records (No. rec.) in the MEM Function menu
  - using the keys



- Selection of the digit to be modified using the W key.
- Modification of the value using the **W** keys.
- Validation of the number of records and exit from the successive menus using the key.

#### <u>Reminder</u>

<u>er</u> The recording capacity is limited to 6,500 measurements (158 for MTX 3281B)


Number of records by default : 1,000.

Reading the Select the Consult menu in the Recordings recorded data Function to view the list or successive records. 28/03/05 10:40:40 Each recording is identified by its start date and time. 28/03/05 10:41:08 Selection of a recording using the 29/03/05 11:05:20 🛄 kevs. 30/03/05 15:30:42 Validation the selection using the 5 val. (2 s), V key. Ø When selected, a recording is accompanied by : - the number of values recorded,

- the recording rate,
- the function in which they were recorded,
- the secondary functions present during recording, if relevant.

<u>Reminder</u> The number of recording sequences is limited to 10.

<u>Viewing the data</u> in a recording The curve displayed is adapted to the graphical window according to its min. and max. values and the number of recordings.



# Access to secondary functions



Choice of secondary functions on the two displays 2, 3 and 4 by pressing successively on the key opposite according to main measurement. A long pressing deletes the display of secondary measurements.

For the main authorized measurements, the last combination selected for displays 2, 3 and 4 is memorized and will be directly reactivated.

# Table of secondary functions Refer to page 9. Disp Function

Refer to page 9.	e 9. Display 2		Display 3		Disp	olay 4	Display 1: Main measurement					
	Functio	n Unit	Function	Unit			VAC VAC+DC	VDC	AAC AAC+DC	ADC	Hz	Ω
MTX 3281B / 2 / 3	FREQ	Hz	PER	S	Func.	MATH	x		x			
MTX 3283B	FREQ	Hz	dB	dB	Func.	MATH	х					
MTX 3283B	dBm	dBm	REF (dBm)	Ω	Func.	MATH	х					
MTX 3281B / 2 / 3	Pk+	V or A	Pk-	V or A	CF	-	х		х			
MTX 3283B	w	W	REF <i>(Ω</i> )	Ω	Func.	MATH	x	х	х	х		
MTX 3281B / 2 / 3	PER	S	DC+	%	Func.	MATH					x	
MTX 3281B / 2 / 3	PER	S	DC-	%	Func.	МАТН					х	
MTX 3282B / 3	PW+	S	CNT+	-	Func.	МАТН					х	
MTX 3282B / 3	PW-	S	CNT-	-	Func.	MATH					х	
MTX 3282B / 3	Func. N	IATH	-	-		-						х
MTX 3282B / 3	V × A	VA	Α	А	Func.	MATH	X (*)	х				

Function MATH = y = Ax + B (MTX 3282B, MTX 3283B)

**FREQ** = Frequency measurement

- PER = Period measurement
- dB = Measurement of voltage decibels in dB
- dBm = Measurement of power decibels in dBm with REF = dBm REF
- **Pk+** = Measurement of positive peaks ( \*\*)
- **Pk-** = Measurement of negative peaks ( \*\*)
- CF = Measurement of peak factor
- **w** = Calculation of resistive power with REF = W REF
- V x A = Calculation of power ( \*) limited to 400 Hz
- **DC+** = Measurement of positive duty ratio  $\Box$
- **DC-** = Measurement of negative duty ratio
- PW+ = Measurement of pulse-width or of positive durations \_\_\_\_
- PW- = Measurement of pulse-width or of negative durations
- **CNT+** = Counting of positive pulses \_□\_ ( \*\*)
- CNT- = Counting of negative pulses ☐ ( \*\*)
  - \*\*) Measurement reset to zero: by pressing on W key.

For optimal use, refer to §. Technical Specifications.

(

Access to secondary functions (cont'd)

MTX 3283B

Upon activation of **dB** measurements, the value measured is taken as voltage reference (V ref).

The calculation is as follows:

20 log<sub>10</sub> (V measured / V ref).

#### The voltage reference (V ref) cannot be modified.


The MATH function is displayed when its parameters allow it (see MATH Func.).

For the dBm and resistive power measurements, see **Measurement** menu for the adjustment of related reference resistances (**dBm REF**, **W REF**) and to know the calculation formulas.

MTX 3282B MTX 3283B

The calculation of power  $V \times A$  (VA) requests a 3rd connection to the A input (connected to the same circuit) in order to measure simultaneously: DC voltage (main display), DC power (display 3, measurement always in AC+DC).

The link on the COM input must be short and have a large diameter in order to limit the voltage drop which influences the Volt measurement.



#### **MATH** function

- MTX 3282B MTX 3283B
- The MATH function (y = Ax + B) enables measuring any physical quantity in: - Volts

(0 - 10 V process or high-voltage probe, for example) - Amperes

(current loop 4 - 20 mA or current clamp, for example)

- Frequency (output measurement, rotation speeds, for example) (resistive position, for example)

- Ohms

and converting it and to assign the adequate unit, to obtain the direct reading of the original parameter on the instrument. Depending on the parameter measured, the device calculates the related MATH function.

The programming takes place in 4 phases:

Selection of parameter X measured (V, A, Ω, Hz) Definition of coefficient A of function v = Ax + BDefinition of coefficient B of function y = Ax + BDefinition of physical unit to be displayed

æ Coefficients A, B and the unit are programmable for each amount measured (V, A, Ω, Hz).

Adjustment of MATH function

- The **MATH** mode is configured in the MATH function in the **Configuration** Menu.
- Opening of **Configuration** Menu using key *2*.
- Selection of function MATH Func. using keys

Configuration	
General 🕂	
Measure 🗕	
Func. 🙂 🛛 🗕 🚽	
Func. MATH 🕁	
MATH function settings	

• Validation of **MATH Func.** using key


Selection of Function menu using keys

Selection of function to be adjusted

MATH function						
Function	V					
Coef A	•					
Coef B	•					
Unit	•					
Function to be set						

- Selection of measurement (V, A, Ω, Hz) using key
- ø Default function V.


- Definition of coefficient A
- The MATH function applied to the physical quantity (x) measured is y = Ax + B.
- Selection of the coefficient A menu (Coef A) in MATH function.
  - Validation of Coef A (coefficient A) using key



- Selection of digit to be modified or of exponent using key I
- Modification of value using keys
- Validation of coefficient A and menu exit using key 2.
- Coefficient A by default is 1.

Definition of coefficient B

- Selection of coefficient B menu (Coef B) in MATH function.
- Validation of Coef B (coefficient B) using key




- Selection of digit to be modified using key
- Modification of value using keys
- Validation of coefficient B and menu exit using key
- d Coefficient B by default is 0.

#### Definition of unit

The unit of the MATH function may be defined so as to obtain the direct reading of the original physical quantity measured by the instrument.

- Selection of Unit menu in MATH function.
- Validation of Unit using key



- Selection of letter or character to display using key .
- Validation of letter or character using keys
- Validation of the unit (3 characters max.) and menu exit using key 2.

The symbol **A** is used to switch from uppercase letters to lowercase.

The symbol 🔄 is used to erase the last character.

MATH unit by default (without).

Function 😳	The favorite function $\textcircled{O}$ recalls directly the specific measurement you use most frequently and that you will have carefully defined previously. This function is of the same type as the <b>MATH</b> function (y = Ax + B). When you measure any physical quantity, this function enables you to convert it and to assign the appropriate unit, to obtain the direct reading of the original amount on the instrument. Depending on the amount measured, the device calculates the related function $\textcircled{O}$ , if the parameters of the latter correspond to the amount measured.
	<ul> <li>Programming takes place in 4 stages:</li> <li>1. Selection of the amount X measured (V, A, Ω, Hz)</li> <li>2. Definition of coefficient A of function y = Ax + B</li> <li>3. Definition of coefficient B of function y = Ax + B</li> <li>4. Definition of the physical unit to be displayed</li> </ul>
Application of the favorite function acc. to its programmed measurements (V, A, Ω, Hz)	<ul> <li>Access to the type of measurement using key ©</li> <li>AC, DC or AC+DC for measurements V and A</li> <li>Access to the frequency range using key ©</li> <li>Frequency &lt; 900 kHz (default) or &gt; 900 kHz for Hz measurements</li> <li>Control of operating modes using key Range:</li> <li>AUTO, AUTO PEAK, MANU for V and A measurements</li> <li>AUTO, MANU for Ω measurements</li> </ul>
	<ul> <li>Pressing one of the keys will switch directly to MANUAL mode, then modify the range for measurements V, A and Ω. Modification of the voltage range for Hz function.</li> <li>Control of display holding using key Hold:         <ul> <li>HOLD, AUTO HOLD, NO HOLD for V and A measurements</li> <li>HOLD, NO HOLD for Ω, Hz measurements</li> </ul> </li> <li>Activation, deactivation of relative mode using key Surv</li> <li>Activation, deactivation automatic recording using key Mem</li> </ul>
<u>Adjustment of</u> <u>function ☺</u>	<ul> <li>The function is configured in Func. <sup>(c)</sup> in the Configuration Menu.</li> <li>Opening of Configuration Menu using key <sup>(c)</sup>.</li> <li>Selection of function Func. <sup>(c)</sup> using keys <sup>(l)</sup>. Validation using key <sup>(c)</sup>.</li> </ul>
	Configuration         General       ➡         Measure       ➡         Func. ③       ➡         Func. MATH       ➡


Function <sup>(2)</sup> setting

bopens directly the Function 😊 menu.

ø

A long press on

<u>Selection of</u> <u>adjustment</u> parameters Selection of adjustment parameters using keys



<u>Selection of amount</u> <u>measured (function)</u>

- Selection of Function menu using keys
- Selection of amount measured (V, A, Ω, Hz) using key
- Default function V.


Definition of coefficients A, B and unit

The O favorite function applied to the physical quantity (x) measured is the same as the MATH function (y = Ax + B).


For the definition of coefficients  ${\bf A},\,{\bf B}$  and the **unit**, see the related menus of the MATH function.

Defficient A is by default 1, B by default 0, unit by default (without).

Example: activation of favorite function and automatic recording mode



SX-DMM Software kit	These multimeters can interface directly with a computer or a PC using the SX-DMM software kit (Cat. # 2125.80 option):					
(option)	In the menu General settings of the multimeter:					
	- Select infra-red communication (IR by default) using the Comm function.					
	<ul> <li>Select the infra-red transmission speed using the IR baud function: 9600 / 19,200 / 38,400 Bauds/s.</li> </ul>					
	The transmission speed by default is 9600 Bauds/s.					
	The other transmission parameters are set (8 data bits, 1 stop bit, no parity).					
Connection of optical cables RS232-DB9F or USB (option)	<ol> <li>Then connect the optical cable to the optical input of the multimeter (located next to the multimeter inputs). A mechanical failsafe prevents reversing of the connection direction. Connect cable RS232-DB9F or USB to one of the corresponding inputs of the PC.</li> </ol>					
	<ol><li>Verify that the RS232 interface parameters of the PC are identical to those of the multimeter.</li></ol>					
	Connector DB9F or USB Interface cable					



*For the USB optical cable (option), install, if necessary, the recognition software on your PC (see CD-Rom MANUAL provided).* 

#### Installation of SX-DMM software

- 1. Install the SX-DMM software on the PC using the CD ROM.
- 2. Launch the software to perform data acquisition and study the different display possibilities (curves, tables...).
- The symbol (RS232) flashes on the display during control of the instrument from the PC (REMOTE mode).

For more information, refer to software help menu.

In this mode, the multimeter keyboard is locked, except for key which is used to exit this mode.

Bluetooth (on -BT version)	The -BT versions of the multimeters are fitted with a Bluetooth module. They integrate the Serial Port Profile service used to communicate with a computer fitted with any type of Bluetooth adapter.
	If your computer does not have a Bluetooth module, the PC USB/Bluetooth adapter (Cat. # 2125.84) is required. To install these pilots, <i>refer to the accompanying instructions.</i>
	Virtual RS232 serial communication between the multimeter (Server) and the PC (Customer) requires a connection on the PC side.
	No configuration is required on the multimeter side, except for activation of Bluetooth (BT) communication via the Comm. function in the <b>General Settings</b> menu.

## Functional description (cont'd)

#### **Bluetooth (cont'd)**

#### Creating a Bluetooth connection

ø The controls cited below are those of the PC USB/Bluetooth adapter (P01637301). They may be designated differently on another adapter.

(for first	Steps	Actions							
connection only)	1	Power up the multimeter.							
	2	Configure it for Bluetooth (BT) via the configuration menu.							
	3	Create a new connection using the software controlling your Bluetooth dongle on the PC side by:							
		<ul> <li>clicking on the Bluetooth Manager icon on the menu bar at the bottom of the screen</li> </ul>							
		<ul> <li>selecting the New connection function</li> </ul>							
		• selecting Express Mode (recommended), then clicking on Next							
		<ul> <li>selecting the Bluetooth peripheral of the multimeter then by clicking on Next</li> </ul>							
		<ul> <li>clicking on Next after configuration of a COM port</li> </ul>							
		<ul> <li>redefining the name of the connection and its icon (if required) then clicking on Next</li> </ul>							
	clicking on <b>Finish</b> to save the connection information								
	You can verify that the connection has been created by viewing it, using the software controlling your PC USB/Bluetooth adapter.								
		tional information, refer to the Help menu [Connect] [Disconnect]							
		ome Bluetooth adapters, rebooting of the PC is recommended to te the connection.							
		onnection parameters are specific to each multimeter. must be assigned MANUALY, but only the first time.							
🔌 Example	configura	ication with SX-DMM software can begin without other Bluetooth tions. You must simply establish communication between the PC and meter using the COM port configured previously.							
	<u>Cor</u>	<u>nmand SX-DMM software</u> : Communication → Parameters							
Reactivation of the connection after shutdown	<ul> <li>Click on the Bluetooth Manager icon on the menu bar at the bottom of the screen</li> <li>Click on the icon related to the multimeter in the window of the Bluetooth</li> </ul>								
	Fdla	ameters Software: the icon of the menu bar must be displayed in green.							
Communication with several		JSB/Bluetooth adapter is used to communicate simultaneously with nultimeters in the MTX Mobile family.							
multimeters		multimeter, you must repeat the previous configuration procedure, king sure to assign them a different COM port.							
	🕙 Depe	nding on the type of adapter, first make a COM port available.							

## **Technical specifications**

"n% of reading + n Digit"

Accuracy: Only the values assigned a tolerance or a limit constitute guaranteed values. "n% +nD" means Values without tolerance are given for information (standard NFC 42670). The technical specifications are guaranteed only after 30 min warm-up period. (as per IEC 485) Except special indication, they are valid from 5 to 100% of the range of measurement.

#### Voltage measurement

#### AC voltage VAC and VAC+DC TRMS

On this position, you measure the true RMS value of an AC voltage with its DC component (no capacitive coupling): so-called TRMS measurement.

MTX 3281B		Input	Resolution	Protection	Accuracy				
	Range	impedance			45 Hz to 1 kHz	1 kHz to 4 kHz	4 kHz to 20 kHz	20 kHz to 50 kHz	
	100 mV (*)	1GΩ - 10MΩ	1 µV	(1 mn max)	1% of R ± 40cts		4% of R ± 6% of R 40cts 40cts		
	1000 mV	10.5 MΩ	10 µV		40013	3% of R ± 40cts			
	10 V	10.5 MΩ	0,1 mV	1450 Vpk					
	100 V	10 MΩ	1 mV	1450 VPK					
	1000 V (**)	10 MΩ	10 mV		1% 01 K ± 400ls				

#### The 100 mV range is present in MANUAL mode only.

(*) In VAC mode		Input impedance	Resolution	Protection	Accuracy			
	Range				45 Hz to 400 Hz	400 Hz to 4 kHz	4 kHz to 20 kHz	20 kHz to 50 kHz
	100 mV	10 MΩ	1 µV	1450 Vpk (1mn max)	1.5% of R ± 40cts	3% of R ± 40cts	4% of R ± 40cts	6% of R ± 40cts

MTX 3282B		Input					Accu	racy		
	Range	impedance	Resolution	Protection	45 Hz to 1 kHz	1 kHz to 4 kHz	4 kHz to 20 kHz	20 kHz to 50 kHz	50 kHz to 75 kHz	75 kHz to 100 kHz
	100 mV (*)	1GΩ - 10MΩ	1 µV	(1 mn max)	1% of R ± 40cts				7% of R ± 40cts	10% typ of R ± 40cts
	1000 mV	10.5 MΩ	10 µV		0.5% of R ± 40cts	2.5% of D	3.5% of R ±	5% of R ±	10% of R ± 40cts	
	10 V	10.5 MΩ	0,1 mV	1450 Vpk	0.3% of P +	± ± 40cts	40cts	40cts	15% of 7% of R ± 40ct	15% of R ±
	100 V	10 MΩ	1 mV	1450 VPK						40cts
	1000 V (**)	10 MΩ	10 mV		0.5% of R ± 40cts				40cts	

#### (\*) In VAC mod

ae	_	Input impedance		Protection	Accuracy						
	Range		Resolution		45 Hz to 400 Hz	400 Hz to 14 kHz	1 kHz to 20 kHz	20 kHz to 50 kHz	50 kHz to 75 kHz	75 kHz to 100 kHz	
	100 mV	10 MΩ	1 µV	1450 Vpk (1mn max)	1.5% of R ± 40cts	2.5% of R ± 40cts	3.5% of R ± 40cts	5% of R ± 40cts		15% typ of R ± 40cts	

MTX 3283B		Input						Accuracy				
	Range	impedance	Resolution	Protection	45 Hz to 1 kHz	1 kHz to 4 kHz	4 kHz to 20 kHz	20 kHz to 50 kHz	50 kHz to 75 kHz	75 kHz to 100 kHz	100 kHz to 200 kHz	
	100 mV (*)	1GΩ - 10MΩ	1 µV	(1 mn max)	0.5%of R ± 40ct	2.5%of R ± 40cts	3% of R ± 40cts	4% of R± 40cts		7% typ of R ± 40cts	10% typ. of R ± 40cts	
	1000 mV	10.5 MΩ	10 µV			1.5%of R ± 40cts	2.5% of R ± 40cts	3.5% of R ± 40cts	5% of R±	8% typ.of R ± 40cts	20% typ.of R ± 40cts	
	10 V	10.5 MΩ	1450 Vnk	0.3%of R ±				40cts		10% of R ±		
	100 V (**)	10 MΩ	1 mV	1450 VPK	40cts	1%of R ±					7% of R ±	30cts
	1000 V (**)	10 MΩ	10 mV		0.4%of R ± 40cts	40cts	40cts	40cts		40cts	15% of R ± 40cts	
(*) In VAC mode		Input						Accuracy				
	Range	Input impedance	Resolution	Protection	45 Hz to 400 Hz	400 Hz to 4 kHz	4 kHz to 20 kHz	20 kHz to 50 kHz	50 kHz to 75 kHz	75 kHz to 100 kHz	100 kHz to 200 kHz	
	100 mV	10 MΩ	5 µV	1450 Vpk (1mn max		3% of R ± 40cts	3.5% of R ±40cts	4% of R ± 40cts	5% of R ± 40cts		10% typ.of R ± 40cts	

### **Technical specifications (cont'd)**

AC voltage VAC and VAC+DC TRMS	<ul> <li>(**) BP : Freq [kHz] limited to : 15,000 / U applied [V] U applied [V] limited to : 15,000 / Freq [kHz]</li> <li>&gt; Example : U applied = 1000 VAC → max. frequency : 15,000 / 1000 = 15 kHz</li> </ul>								
(cont'd)	In the presence of a continuous component :								
	Additional error: (UDC / U measured) x (0,7% of reading + 70cts)								
	Sector Secto								
	Rejection: common mode > 80 dB at 50 Hz or 60 Hz depending on selection								
	Automatic or MANUAL selection of ranges.								
	Protection by varistors.								
	Maximum permanent acceptable voltage: 1000 VACrms.								
	Specifications valid from:								
	20 to 100% of range in the 20 kHz to 200 kHz MTX 3283B band,								
	20 kHz to 100 kHz MTX 3282B								
	20 kHz to 50 kHz MTX 3281B.								
	As soon as the PEAK symbol is displayed, connect to AUTO PEAK :								
	MTX 3282BMTX 3283B								
	Influence of peak factor on accuracy in VAC, VAC+DC at 50% of the range:								

- •1% for a peak factor between 4,5 and 6
- 5% for a peak factor between 6 and 9

DC	voltage
	VDC

In "DC" mode, you measure the value of a DC voltage or the DC component of
 an AC voltage, once the filter is activated, see p. 15.

#### The 100 mV range is present in MANUAL mode only.

MTX 3281B	Range	Input impedance	Resolution	Protection	Accuracy
	100 mV (*) 10 MΩ / 1 GΩ		1 µV		0.1% of R + 30cts
	1000 mV	20 MΩ / 1 GΩ	10 µV		
	10 V	10.5 MΩ	0.1 mV	1450 Vpk	0.1% of R + 8cts
	100 V	10 MΩ	1.0 mV		
	1000 V	10 MΩ	10 mV		0.2% of R + 8cts

MTX 3282B	Range	Input impedance	Resolution	Protection	Accuracy
	100 mV (*)	10 MΩ / 1 GΩ	1 µV		0.1% od R + 30cts
	1000 mV	20 MΩ / 1 GΩ	10 µV		0.05% of R + 8cts
	10 V	10.5 MΩ	0.1 mV	1450 Vpk	0.03% of R + 8cts
	100 V	10 MΩ	1.0 mV		0.03% OF R + OCIS
	1000 V	10 MΩ	10 mV		0.035% of R + 8cts

MTX 3283B	Range	Input impedance	Resolution	Protection	Accuracy
	100 mV (*)	10 M $\Omega$ / 1 G $\Omega$	1 µV		0.1% of R + 30cts
	1000 mV	20 MΩ / 1 GΩ	10 µV		0.05% of R + 8cts
	10 V	10.5 MΩ	0.1 mV	1450 Vpk	0.02% of D + Poto
	100 V	10 MΩ	1.0 mV		0.02% of R + 8cts
	1000 V	10 MΩ	10 mV		0.03% of R + 8cts

(\*) - Accuracy with filter (p. 15) and REL mode activated ( $\Delta$  measurement).

Recovery after release of the protection (> 10 V) approx. 10 s.
 Protection 1 min. max.

- Frotection Thin. max.

Specifications valid from 0 % to 100 % of the range

Rejection:common mode:> 120 dB with 50 Hz and 60 Hz acc. to selectionserial mode:> 60 dB with 50 Hz and 60 Hz acc. to selectionAutomatic or MANUAL selection of the ranges. Protection by varistors.

## Technical specifications (cont'd)

#### **Current measurement**

ADC current

In "ADC" mode, you measure the value of a DC current or the DC component of an AC current.

MTX 3281B MTX 3282B MTX 3283B

Range	Input impedance	Resolution	Protection	Accuracy	
1000 µA	approx. 170 $\Omega$	10 nA		0.1% of R + 15cts	
10 mA	approx. 17 $\Omega$	0.1 µA		0.08% of R + 8cts	
100 mA	approx. 1.7 $\Omega$	1 µA	11 A	0.00% OF R + 6015	
1000 mA	approx. 0.17 $\Omega$	10 µA	20 A < 30 s	0.15% of R + 8cts	
10 A		100 µA		0.5% of R + 15cts	
100 A (**)	approx. 0.03 Ω (*)	1000 µA		0.5% OFR + 1501S	

(\*) with the fuse delivered with the instrument

(\*\*) 100 A range limited to 20 A

Specifications valid from 0 % to 100 % of range

*AAC current,* In "AAC" and "AAC+DC" modes, you measure the true RMS value of an AC current with/without its DC component (no capacitive coupling in "AC+DC" mode).

MTX 3281B

Dense	Input	Resol.	Drotoot	Accuracy				
Range	Range impedance		Protect.	45 Hz to 1 kHz	1 kHz to 4 kHz	4 kHz to 20 kHz		
1000 µA	approx. 170 $\Omega$	10 nA		1% of R ± 40cts		5% of R ± 30cts		
10 mA	approx. 17 $\Omega$	0.1 µA		1% of R ± 30cts	1.5% of R ± 30cts			
100 mA	approx. 1.7 $\Omega$	1 µA	11 A		1.5% ULK ± 30005	3% of R ± 30cts		
1000 mA	approx. 0.17 $\Omega$	10 µA	20A<30s					
10 A	approx. 0.03 Ω	100 µA		1.5% of R ± 30cts	3% of R ± 30cts	5% of R ± 30cts		
100 A (**)	(*)	1000 µA		2.5% of R ± 30cts	5 % 01 K ± 3001S	5 /0 ULK I SUCIS		

МТХ	3282E
MTX	3283E

2B	Danga	Input	Resolution	Protection	Accuracy					
3B	Range	impedance	Resolution	Protection	45 Hz to 1 kHz	1 kHz to 4 kHz	4 kHz to 20 kHz	20 to 50 kHz		
	1000 µA	approx. 170 Ω	10 nA		0.5% of R ± 40cts	1% of R± 30ctcs	5% ± 30D	-		
	10 mA	approx. 17 $\Omega$	0.1 µA	11 A 20A < 30s	0.3% of R ± 30cts			5% of R ± 30cts		
	100 mA	approx. 1.7 $\Omega$	1 µA			1.5% of R ±		5% 01 K ± 30ClS		
	1000 mA	approx. 0.17Ω	10 µA			30cts	3% of R ± 30cts			
	10 A	approx.	100 µA		1.5%of R± 30cts	00/ CD 00 1	]	-		

(\*) with the fuse delivered with the instrument

(\*) 100 A range limited to 20 A

In presence of a continuous component :

additional error : (I DC / I measured) x (0.7% of reading + 70cts)



A max. overload of 20 A is acceptable for 30 s max. with a pause of 5 min at least between each measurement.

From 7 A, the measurement is limited to an ambient temperature of 40° C and a period of 1h30 with a pause of 15 min at least between each measurement.

Specifications valid from 10% to 100% of range for sinusoidal current.

Protection	1000 Vrms by ceramic HRC type fuse
Fuse	1000 V, 11 A > 20 kA Cos $\phi$ > 0.9 (10 x 38 mm)

MTX 3282B

🖉 As soon as the PEAK symbol appears, switch to AUTO PEAK mode :

#### MTX 3283B <u>mA and µA range</u>:

Additional error of 2% for a peak factor between 4.5 and 6<br/>Additional error of 15% for a peak factor between 6 and 9<br/>
<hr/>
<

## **Technical specifications (cont'd)**

#### Frequency

measurement

Main frequency (Hz)

In this position, you measure the frequency of a voltage.

AC Signals

MTX 3281	В
MTX 3282	В
MTX 3283	В

	Range	ge R		esolution	Protection		Accuracy		
	0.8 to 10 Hz	Z	0	.0001 Hz	001 Hz				
	10 to 100 H	z	C	).001 Hz					
	100 to 1000 H	Ηz		0.01 Hz					
	1000 Hz to 10	kHz		0.1 Hz	1450 Vpk	1450 Vpk 0.02% of R:		0.02% of R± 8cts	
	10 to 100 kH	z		1 Hz					
	100 to 1000 k	Hz		10 Hz					
	1 MHz to 2 M	/Hz to 2 MHz		100 Hz					
Range Sensitivity (applicable on rectangular					· signals only)				
	Range	10	0 mV	1 V	10 V		100 V	1000 V	
	0.8 Hz to 10 Hz	15 %	of range	25 % of range	15 % of range	15 %	o of range	15 % of range	
	10 Hz to 100 kHz	10 %	of range	20 % of range	10 % of range	10 %	o of range	10 % of range (*)	
	100 to 500 kHz		(**)	20 % of range	typ. 20 % of range	20 % of range (*)		20 % of range (*)	
	500 to 1000 kHz				typ. 30 % of range				
	1 MHz to 2 MHz		-	-	typ. 50 % of range		-	-	

(\*) Freq [kHz] limited to: 15,000 / U applied [V]

U applied [V] limited to: 15,000 / Freq [kHz]

(\*\*) limited to 200 kHz

The measurement is performed by capacitive coupling.

Selection of the MANUAL frequency range < 900 kHz (default) or > 900 kHz,

via a short pressing of the key opposite.

Selection of voltage range in MANUAL mode possible, via a long pressing of the key *opposite*.

Input resistance:  $\approx$  10 M $\Omega$  (Freq < 100 Hz)

Maximum permanent acceptable voltage: 1000 Vrms. See (\*).

Protection by varistors at the voltage input

Parallel voltage or current or frequency (secondary function)



You measure the free	equency and value	alue of a voltage or a current.			
Range	Accuracy	Resolution	Admissible overload		

range	recolutor				7 (0111)			
0.8 to 10 Hz	0.02 % or R + 8cts		0.0001	Hz				
10 to 100 Hz			0.001	Hz				
100 to 1000 Hz			0.01 H	Ηz		1450 Vdc		
1000 to 10 kHz			0.1 H	z	01	(1 min max.) n 500 mV range		
10 to 100 kHz			1 Hz	2				
100 to 200 kHz			10 H	lz	1			
Range	Sensitivity (applicable on rectangular signals only) Vrms							
Range	100 mV	1 V		10 V to 1	000 V (*)	1000 µA to 20 A (**)		
0.8 Hz to 5 kHz	15 % of range	20 % of range		20 % of range		15 % of	range	20 % of range
5 kHz to 50 kHz	10 % of range	20 % of range		20 % of range		10 % of	range	20 % of range
50 kHz to 100 kHz	15 % of range	25 % of range		inge 15 % of range				
100 kHz to 200 kHz	-	30 % of range		30 % of	range	-		

(\*) Freq limited to [kHz]:

15,000 / U applied [V]

U applied [V] limited to [V]: 15,000 [V \* kHz] / Freq [kHz]

(\*\*) limited to 20 kHz MTX 3281B ; at 50 kHz MTX 3282B, MTX 3283B for the "Ampere" range

Measurement is performed by capacitive coupling Input resistance:  $\approx 10 \text{ M}\Omega$  (Freq < 100 Hz) Protection by varistors at voltage input

Resistance m

In this position, you measure the value of a resistance.

٦e	as	ur	em	lei	nt (	[Ω]	

nent (Ω) MTX 3281B	Range	Accuracy	Resolution	Protection
	1000 Ω		10 mΩ	
	10 kΩ	0.1 % of R + 8cts	100 mΩ	
	100 kΩ	0.1 % 01 R + octs	1 Ω	1000 Vrms
	1000 kΩ		10 Ω	1000 VIIIIS
	10 MΩ	0.5 % of R+ 8cts	100 Ω	
	50 MΩ	2 % of R+ 8cts	1 kΩ	

#### MTX 3282 MTX 328

2B 3B	Range	Accuracy	Resolution	Protection
30	1 000 Ω	0.1 % of R + 8cts	10 mΩ	
	10 kΩ		100 mΩ	
	100 kΩ	0.07% of R + 8cts	1 Ω	1000 Vrms
	1000 kΩ		10 Ω	
	10 MΩ	0.5% of R + 8cts	100 Ω	
	50 MΩ	2 % of R + 8cts	1 kΩ	

Automatic/MANUAL range selection "Active" protection via CTP thermistor Measurement voltage: ca. 1.2 V

Maximum voltage developed on open circuit: 4 V typ

- ø In range 50 M $\Omega$ , in order to avoid the influence of the network and to guarantee the given specifications, it is advised to disconnect the multimeter from Wall Plug.
- ø For measurements higher than 10  $M\Omega$ , a shielded cable is recommended. For a 2 wire-link, use very short wires (< 25 cm) and twist them.



On this position, you can measure the value of a resistance up to 1000  $\Omega$ , with steady audio indication at 2 kHz.

2B	Range	Accuracy	Measuring current	Resolution	Protection
3B	Beeper	0.1% of R + 8cts	approx. 0.4 mA	100 m $\Omega$	1000 Vrms

Detection threshold in continuity mode  $\approx$  120  $\Omega$  (response time  $\approx$  5 ms). "Active" protection via CTP thermistor.

Maximum voltage on open circuit: 4 V max, 2 V typ.



Indication of junction voltage in the direction from 0 to 2.6 V in a single range (10 V range)

Accuracy Resolution	2 % of reading ± 30cts 0.1 mV
Measuring current	< 1 mA
Maximum voltage developed on open circuit	4 V max.
"Exceeded" indication	in reverse direction
"Active" protection by CTP thermistor	1000 Vrms

	citance
measu	urement
(++)	urement

In this position, you can measure the value of a capacitor.

· · F. · · · · · · · · · · · · · · · · ·					
Range	Accuracy	Resolution	Measurement time	Protection	
10 nF (*)	1 % of r + 10cts	10 pF	< 0,2 s		
100 nF		100 pF	< 0,5 s		
1000 nF	1 % of reading +	1 nF			
10 µF	5cts	10 nF	< 2 s	1000 Veff.	
100 µF		100 nF			
1000 µF	1 % of r+ 15cts	1 µF			
10 mF	1.5 % of r+15cts	10 µF	≈ 5 S/IIIF		
	10 nF (*) 100 nF 1000 nF 10 μF 100 μF 1000 μF	10 nF (*)         1 % of r + 10cts           100 nF         1 % of reading +           1000 nF         1 % of reading +           10 μF         5cts           100 μF         1 % of r+ 15cts	10 nF (*)         1 % of r + 10cts         10 pF           100 nF         100 pF         100 pF           1000 nF         1 % of reading +         1 nF           10 μF         5cts         10 nF           100 μF         100 nF         100 nF           100 μF         5cts         10 nF           100 μF         100 nF         100 nF	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $	

(\*) Use the REL function for values < 10 % of range to reset to residual zero (compensation of the test lead capacity)

Resolution of 1000 points. Automatic/MANUAL range selection. "Active" protection by CTP thermistor. Maximum voltage delivered on open circuit: 1 V typ. / 4 V max.

For measurements lower than 10 nF, a shielded cable is recommended. For a 2 wire-link, use very short wires (< 25 cm) and twist them.

**Temperature** measurement with Pt 100 or Pt 1000

In this position, you measure a temperature via a Pt 100 or Pt 1000 sensor.

Range	Measuring current	Resolution	Accuracy	Protection
- 125°C to + 75°C	< 0.8 mA (Pt 100) < 0.5 mA (Pt 1000)	0.1%0 0.01	$\pm$ 0.5°C	1000 Vrms
- 200°C to + 800°C	< 0.8 mA (Pt 100) < 0.5 mA (Pt 1000)	$0.1^{\circ}C \equiv 2\mu V$	0,1 % ±  1°C 0,07 % ± 1°C	

#### "Active" protection by CTP thermistor

Internal measurement accuracy

Reference temp. accuracy

Thermocouple K

Thermocouple J

Resolution

Protection

Display in ° C (Celsius) / K (Kelvin) / ° F (Fahrenheit) possible

In this position, you measure the temperature via a thermocouple:

In Temperature measurement, it is possible to modify the scale of the graphic window with the keys  $\blacksquare$  . The selected scale is recalled in the help line i.

Temperature	
measurement with	
thermocouple J or K	

MTX 3281B MTX 3282B MTX 3283B

MTX 3282B MTX 3283B

dBm measurement (power decibels)

MTX 3283B

MTX 3283B

Type of thermocouple J and K The multimeter needs 60' to adapt to the ambient temperature. Display of measurement in dBm in relation to a resistance reference (**dBm REF**) adjustable from 1  $\Omega$  to 10,000  $\Omega$ , factory set at 600  $\Omega$ . Resolution 0.01 dB Absolute error in dB 0.09 x VAC relative error expressed in % Additional calculation error 0.01 dB Measuring range 10 mV to 1000 V 1000 Vrms Protection Display of measurement in dB with the value measured (V ref) at activation of

dB measurement (voltage decibels)

the mode as voltage reference. 0.01 dB Absolute error in dB 0.09 x VAC relative error expressed in % Additional calculation error 0.01 dB 10 mV to 1000 V Measuring range 1000 Vrms

from -40° C to +1200° C

± 3° C ± 0.1% fs (-10° C to 55° C)

from  $-40^{\circ}$  C to  $+750^{\circ}$  C

± 3° C / typical value

Peak measurement	Secondary values	Peak ranges	Additional error	Protection			
Pk+	Peak V t > 250 µs	100 mV to 1000 V	3%of R ± 50cts	1000 Vrms			
Pk-	Peak A t > 250 µs	1000 µA to 20 A	4% of R ± 50cts	or 10 Arms			
MTX 3281B MTX 3282B MTX 3283B	Specifications valid from 20 % of the range in A, 10 % of the range in V The value of the peak factor results from calculation: $(Pk+ - Pk-) / 2 \times Vrms$ Additional error for 250 µs < t < 500 µs: 3% Measurement zero reset: by pressing the key .						
SURV Function (MIN, MAX, AVG)	Accuracy and rate: i		It and Ampere measur <mark>3B</mark>	ements			
Resistive power W	$\begin{array}{llllllllllllllllllllllllllllllllllll$						
Power calculation V x A MTX 3282B MTX 3283B	The current measur Accuracy (typical) : <i>The connection c</i>	ement is always per V measurement a on the COM input m	ent : this calculation erformed in AC+DC. ccuracy + Peak A me ust be short and of larg s Volt measurement.	easurement accuracy			
Duty ratio	Display of the measurement in % of a logic signal (T <u>TL, C</u> MOS)						
	DC+ Duty ratio DC- Duty ratio □		$= \theta$ = T - $\theta$	<b>&gt;</b>			
	Resolution		0.01%				
MTX 3281B	Minimum duration for	or A	10 μs				
MTX 3282B	Maximum duration f		0.8 s				
MTX 3283B	Minimum duration for		200 μs				
	Nominal range	ИІ	5 to 90% typical				
	Sensitivity (10 V ran	ae)	> 30% of the Freq ran	ne < 1 kHz			
		90)	> 50% of the Freq ran				
	Absolute error on th	e duty		0 -			
	ratio, expressed in a	bsolute %	0.05% + 0.0001 / T   0.1% + 0.0005 / T [t ir				
	Additional absolute	error	0.1 x C/P				
	(slope at switching t		C = range in V or in A				
		,	(for range 1000 V, C =				
			P = slope in V/s, A/s	,			
	Protection		1000 Vrms				
Pulse counting	Depending on trigge	ring conditions of fr	equency meter				
CNT+ _	Minimum pulse dura	-	5 μs				
CNT- ] [	Counting up to		99999				
	Triggering threshold		10 % of range except	range 1000 Vac			
MTX 3282B MTX 3283B	This threshold is:		positive in <i></i> , negativ	e in ℃			
	Counter reset to zer	0	by pressing the key				
đ	For negative events	, reverse the cables					

Pulse width PW+ PW MTX 3282B MTX 3283B	Depending on triggering Resolution Minimum pulse width Accuracy Maximum period duration Triggering threshold	conditions of frequency meter. 10 μs 100 μs 0.05% ± 10 μs 12.5 s 20% of range except range 1000 VAC
ø	This threshold is positive Additional error on measu Measurement of duty rati	urement caused by slope when crossing zero: see §. o.
Clock	MTX 3281B	Relative time with reset to zero at each powering up
	MTX 3282B, MTX 3283E Accuracy Display	<ul> <li>Real-time clock</li> <li>≈ 30 s / month: real-time clock deviation</li> <li>date - month - year / hour - minute - second</li> </ul>
Influences	<ul> <li>Typical specification</li> <li>Specification of the co</li> <li>Δ T: difference betwee the field of reference</li> <li>➤ Example : tempera</li> <li>Δ t ° C = SPEC</li> </ul>	
Multimeter Traceability	TRACEABILITY           Model No. :         3283           Serial No. :         1001           Firmware Vers. :         1001           Hardware Vers. :         100           Hardware Vers. :         C           CALIBRATION         Last Cal. :           27/11/2005         10:08           Next Cal. :         27/11/2006	B 0110 multimeter up-dates: • Model • Serial No • Firmware Version • Hardware Version

**Calibration** A periodic calibration (once a year) of the multimeter is necessary to guarantee the given specification (refer to §. Maintenance, Metrological verification)

### **General characteristics**

Environmental	Altitude	< 2000 m			
Conditions	Reference temperature	23° C ± 5° C			
	Utilization temperature	0° C to 55° C			
	Influence of temperature see §.	Influence			
	Relative humidity	Max 80% for temperature up to 31°C			
		Decreasing linearly to 50% at 40°C Limited to 70% for the $50M\Omega$ range			
	Sealing	IP 51			
	Operating range	- 10° C to 55° C			
	Storage range	- 40° C to 70° C			
	Battery charge range	0 to 40° C			
Power supply					
MTX 3281B	2 possibilities:				
	Batteries	3 x 1.5 V alkaline LR6-AM3 AA			
	<ul> <li>Accumulators</li> </ul>	3 x 1.2 V Ni-MH 2600 mAh AA			
	3 possibilities:				
MTX 3282B	Batteries	3 x 1.5 V alkaline LR6-AM3 AA			
MTX 3283B	Accumulators	3 x 1.2 V Ni-MH 2600 mAh AA			
	<ul> <li>Wall Plug power unit: Mains voltage</li> </ul>	230 V ± 10% or 110 V ± 10%			
	Overvoltage category				
	Frequency	45 Hz - 65 Hz			
	Via the wall plug, the accumulate from the multimeter.	ors can be recharged without removing them			
	Average charging period: 7h30 (	(with 2600 mAh accumulators)			
		(			
Endurance	• with batteries	80 h (VDC mode)			
	<ul> <li>with 2200 mAh accumulators</li> </ul>	approximately 65 h (VDC mode)			
		e multimeter, powering by Ni-MH cells is not nas a self-discharge rate of 100 % after			
¢	Endurances are reduced if the LCD backlight and/or the Bluetooth				
	communications interface is u				
	Oreabia LOD				
Display	Graphic LCD	useful part 58 x 58 mm orientable, LED backlit, transflective improvement of contrast in full light			
	Main display	100,000 points + sign + curve adaptive units + bargraph (40 segments) indicators of modes engaged battery level indicator, dangerous voltage indicator			

secondary functions with adapted units

Secondary display

# General characteristics (cont'd)

Safety	As per CEI 61010-1 Ed. 2 (2001):				
	<ul> <li>Insulation</li> </ul>	class 2			
	<ul> <li>Degree of pollution</li> </ul>	2			
	<ul> <li>Utilization</li> </ul>	interior			
	Altitude	< 2000 m			
	<ul> <li>Measurement category of "measurement" input</li> </ul>				
	<ul> <li>Measurement category of "measurement" input</li> </ul>				
EMC	<ul> <li>This device was designed in accordance with EMC standards in force and its compatibility was tested in accordance with the following standards:</li> <li>Emission (cl. A) and Immunity NF EN 61326-1 (1997); A1 (1998); A2 (2001)</li> </ul>				
	<ul> <li>Max. influence in pre of radiated fields</li> </ul>	sence See §. Influences			
RS232-DB9F or USB optical cables	The optical interface ensures insulation in relation to the connected peripheral (PC) for the transfer of data or for remote control of the multimeter.				
(options)	RS232 communication interface parameters:				
	Transmission speed: 9600 / 19,200 / 38,400 Bauds/s				
	The other transmission parameters are set (8 data bits, 1 stop bit, no parity).				
	USB communication interface: delivered with installation software.				
Bluetooth	Transmission speed	38.4 kbit/s			
(-BT version only)	Sensitivity Max. power	-90 dBm 20 dBm (100 mW)			
	Max. distance	ca. 100 m			
	Battery life	ca. 40 h (VDC mode) with alkaline batteries			
Mechanical cha	aracteristics				
Casing	Dimensions	87.8 x 265.5 x 107.5 mm (open position) 87.8 x 187 x 48.6 mm (casing closed)			
	Weight	0.450 kg approximately			
	Materials	ABS VO (auto-extinguishing) and PC VO			

- external protective moulding in thermoplastic rubber : SEBS IP 51
- Sealing

Packaging • Dimensions

MTX 3281B 240 (	L) x 158 (W) x 65 (H) in mm
MTX 3282B,MTX 3283B	297 (L) x 158 (W) x 60 (H) in mm

### Supply Supply

ouppiy					
Supply					
Delivered with the instrument MTX 3281B (Cat. #2125.71)	<ul><li>Quid</li><li>Set of</li></ul>				
MTX 3282B (Cat. #2125.72)	<ul> <li>Quick Check Guide (bilingual Fr - En)</li> <li>Set of 3 accumulators 1.2 V Ni-MH 2600 mAh</li> <li>Wall Plug power/charger unit</li> <li>Set of silicon test leads - 4 mm safety touch prods</li> </ul>				
MTX 3283B (Cat. #2125.73)	<ul> <li>Quick Check Guide (bilingual Fr - En)</li> <li>Set of 3 accumulators 1.2 V Ni-MH 2600 mAh</li> <li>Wall Plug power/charger unit</li> <li>Set of silicon test leads - 4 mm safety touch prods</li> </ul>				
Supplement delivered with versions MTX 3281B-COM (Cat. #2125.74)	- "I	uisition software kit: Data Viewer" Acquis S232-DB9F Optical	ition software for PC cable		
MTX 3282B-COM (Cat. #2125.75)					
MTX 3283B-COM (Cat. #2125.76)					
Accessories MTX 3283B-BT (Cat. #2125.79)	- "I - R • Blue	uisition software kit: Data Viewer" Acquis S232-DB9F Optical tooth software kit: Iluetooth USB Ada			
Optional Accessories	<ul> <li>Calibration software of the MTX 328x range</li> <li>Acquisition software kit: <ul> <li>"Data Viewer" Acquisition software</li> <li>RS232-DB9F Optical cable</li> </ul> </li> <li>USB Optical cable + installation software</li> <li>Adapter + K thermocouple</li> <li>Ammeter clamps:</li> </ul>				Cat. #2125.82 Cat. #2125.80
					Cat. #2125.81 Cat. #2125.83
	MN213	0.5 to 240 AAC	ratio 1000 /1	40 Hz to 10 kHz	Cat. #2115.75
	SR604	0.1 to 1000 AAC	ratio 1000 /1	30 Hz to 10 kHz	Cat. #2113.44
	MN 373	0.01 to 240 AAC	1mA/mV or 1A/10mV	40 Hz to 10 kHz	Cat. #2116.28
	SL261	0.005 to 80 AAC/DC	1 A/1 V or1 A/10 mV	DC - 8 kHz	Cat. #1201.51
	<ul> <li>Hand-held carrying bag</li> <li>Set of 3, 1.2 V NiMH cell batteries</li> </ul>				Cat. #2125.96
					Cat. #2125.99 Cat. #2125.98
	110V US power supply for MTX series				
	<ul> <li>PC Adapter USB/BLUETOOTH</li> <li>USB optical cable</li> <li>Temperature sensor Pt 1000</li> </ul>				Cat. #2125.84
					Cat. #2135.41 Cat. #2125.85
Spare parts	• Lead		or-coded w/test probe	S	Cat. #2970.92
	{100	0V CAT IV, 15A, UL	.}		Cat. #2125.97

## Index

	Inde	^	
888888 (function)	9	display	9, 42
Α	-	duty ratio	39
absolute deviation	19		
AC voltage	33	E	
AC, AC+DC	7	EMC	42
Accessories	3, 43	endurance	41
accumulators	10-13, 43	energy	11, 12
activation (powered)	6, 10	English (Choice of language)	14
alert	5, 9	environment	3, 41
amount measured	29, 30	erase	24
Ampere (function)	5, 13		
audio warning	5, 14, 18	F	
auto (mode)	18	favorite function	29, 30
auto hold (mode)	8, 18	filter	15
auto peak (mode)	8, 18	French (Choice of language)	14
automatic detection	4	FREQ	22, 25
automatic recording	8, 29	frequency measurement	36
automatic stop	14	main functions	7, 17
AVG	20	secondary functions	9, 25
		fuse	4, 5, 13 ,43
В			1, 0, 10, 10
back-lighting	8, 9, 15	G	
	9		11
bargraph		General (function)	
basic (mode)	15	General (menu)	12, 14
batteries	10	general settings	11, 31, 40
Bluetooth	5, 31, 32, 42	Graphical display	9
buzzer	4, 5, 10, 14	guarantee	4
С		Н	
cable connection	31	help (i)	7, 9, 31, 32
capacitance measurements	5, 7, 9, 17, 38	HOLD (mode)	8, 18
capacitive coupling	33, 35, 36	humidity	3, 41
casing	42	-	
charge (recharge)	10-13	I - J - K	
CNT	25, 39	impedance	8, 15
coef. A, coef. B	27, 28, 29	initial settings	14
COM	5, 17, 18	inputs	9
comm.	31	IR baud	31
communications	5	J (thermocouple)	7
configuration	7, 8, 15-18		
configuration (menu)	15-18	jack connector	6, 12 7
		K (thermocouple)	7
continuity measurement	17	keyboards	6
continuity mode	37	keys	7, 8
current measurement	7, 16, 34		
		L	
D		LCD contrast	8, 9, 14, 41
date	14, 20		
dB measurement	38	М	
db9f	31, 42, 43	main display	19, 41
dBm REF	15	main functions	7, 16, 17, 24
dBm	38	main measurement	18-21
DC voltage	33, 34	maintenance	4
DC	25, 34, 39	MANU (key)	8, 18, 29
diode measurement	17, 37	MATH (function)	25-30
	,		20 00

# Index

MAX	20, 21, 24	temperature measurement	7, 8, 17, 18, 38
measurement category	3	terminal board	6
MEM (function)	9, 23, 24	thermocouple	7, 17
MEM (key)	8	time	13, 14, 20
MEM (mode)	5, 8, 14, 21, 22	traceability	40
memory	24	transient overvoltages	5
MIN	20, 21, 24	type of energy	11
monitoring	29		
		U - V - W	
N - O		unit	26, 27, 28
NO HOLD (mode)	8, 18, 29	Wall plug	12, 13
optical cable	31, 42, 43		
optical link	5		
Р			
parameters	30		
peak factor	18, 25		
peak measurement	39		
PER (period)	25		
Pk (peak)	25		
power supply	12, 14, 41		
power unit (Wall plug)	10, 37, 41, 43		
protection	3, 5, 13		
Pt100 (sensor)	7		
Pt1000 (sensor)	7		
pulse counting	39		
pulse width	40		
•			
R			
range	18		
recharge (charge)	10-13		
recorded data	20, 23		
recording	20-24, 29, 30		
REL	8, 9, 17, 18		
resistance measurement	7, 17, 37		
resistive power	16, 25, 26, 39		
RS 232	5, 9, 31, 42, 43		
110 202	0, 0, 01, 12, 10		
S			
safety	3, 4, 10, 42		
secondary displays	8, 9		
secondary functions	9, 23, 25, 36		
sensor	9, 23, 23, 30 17, 38, 43		
software kit	31		
SPEC (function)	21		
	14		
standby supply	43		
SURV	43 5, 8, 9, 14, 20		
SX-DMM	31, 32		
	51, 52		
т			
TC J (thermocouple)	7, 17		
TC K (thermocouple)	7, 17 7, 17		
temperature	7, 17 3, 11, 33, 35, 40		
iomperature	0, 11, 00, 00, 40		

### **Repair and Calibration**

To ensure that your instrument meets factory specifications, we recommend that it be submitted to our factory Service Center at one-year intervals for recalibration, or as required by other standards or internal procedures.

#### For instrument repair and calibration:

You must contact our Service Center for a Customer Service Authorization number (CSA#). This will ensure that when your instrument arrives, it will be tracked and processed promptly. Please write the CSA# on the outside of the shipping container. If the instrument is returned for calibration, we need to know if you want a standard calibration, or a calibration traceable to N.I.S.T. (includes calibration certificate plus recorded calibration data).

Chauvin Arnoux<sup>®</sup>, Inc. d.b.a. AEMC<sup>®</sup> Instruments 15 Faraday Drive Dover, NH 03820 USA Tel: (800) 945-2362 (Ext. 360) (603) 749-6434 (Ext. 360) Fax: (603) 742-2346 or (603) 749-6309 repair@aemc.com

(Or contact your authorized distributor)

Costs for repair, standard calibration, and calibration traceable to N.I.S.T. are available.

#### NOTE: All customers must obtain a CSA# before returning any instrument.

### **Technical and Sales Assistance**

If you are experiencing any technical problems, or require any assistance with the proper operation or application of your instrument, please call, mail, fax or e-mail our technical support hotline:

Chauvin Arnoux<sup>®</sup>, Inc. d.b.a. AEMC<sup>®</sup> Instruments 200 Foxborough Boulevard Foxborough, MA 02035, USA Phone: (800) 343-1391 (508) 698-2115 Fax: (508) 698-2118 techsupport@aemc.com <u>www.aemc.com</u>

NOTE: Do not ship instruments to our Foxborough, MA address

## **Limited Warranty**

The MTX Multimeters are warranted to the owner for a period of three years from the date of original purchase against defects in manufacture. This limited warranty is given by AEMC<sup>®</sup> Instruments, not by the distributor from whom it was purchased. This warranty is void if the unit has been tampered with, abused or if the defect is related to service not performed by AEMC<sup>®</sup> Instruments.

For full and detailed warranty coverage, please read the Warranty Coverage Information, which is attached to the Warranty Registration Card (if enclosed) or is available at <u>www.aemc.com</u>.

### Please keep the Warranty Coverage Information with your records.

### What AEMC<sup>®</sup> Instruments will do:

If a malfunction occurs within the three-year period, you may return the instrument to us for repair, provided we have your warranty registration information on file or a proof of purchase. AEMC<sup>®</sup> Instruments will, at its option, repair or replace the faulty material.

### **Warranty Repairs**

### What you must do to return an Instrument for Warranty Repair:

First, request a Customer Service Authorization Number (CSA#) by phone or by fax from our Service Department (see address below), then return the instrument along with the signed CSA Form. Please write the CSA# on the outside of the shipping container. Return the instrument, postage or shipment pre-paid to:

Ship To: Chauvin Arnoux<sup>®</sup>, Inc. d.b.a. AEMC<sup>®</sup> Instruments 15 Faraday Drive • Dover, NH 03820 USA Phone: (800) 945-2362 (Ext. 360) (603) 749-6434 (Ext. 360) Fax: (603) 742-2346 or (603) 749-6309 E-mail: repair@aemc.com

Caution: To protect yourself against in-transit loss, we recommend you insure your returned material.

### NOTE: You must obtain a CSA# before returning any instrument.



06/14

99-MAN 100340 v6

Chauvin Arnoux<sup>®</sup>, Inc. d.b.a. AEMC<sup>®</sup> Instruments 15 Faraday Drive • Dover, NH 03820 USA • Phone: (603) 749-6434 • Fax: (603) 742-2346 www.aemc.com