# SX-DMM for MTX Multimeters

Install the USB driver and software. (The software and USB driver are on the CD supplied with the instrument)

1) Install the USB driver before connecting any USB cable.

2) Install the software MX-DMM Version xxx

3) Connect the USB optical cable to the PC

How to find a USB port number with Windows 7

SX-DMM for MTX Multimeters

From START/Control panel/Hardware and sound/Device manager

Remember the com port number and launch SX-DMM

Choose the channel you want to use and enter the com port. It is possible to connect 4 DMM's at the same time.

SX-DMM for MTX Multimeters

Press OK then RUN

The window displays the range selected on the meter. Modify if needed by clicking on the UP and DOWN arrows.

SX-DMM for MTX Multimeters