

PEL 112-113 – Release Notes

v1.14 – 2/05/2026

(Version 1.12/1.13/1.14)

Integration of the Mini94 Clamp into the device

(Version 1.10/1.11)

Improvements to device logging

Addressing missing 1s and 200mS data

(Version 1.09)

PEL 115 devices – the REC LED had been blinking once every 5s instead of every second

(Version 1.08)

PEL 115 devices IN was always computed as the sum I1+I2+I3, even if a sensor was connected on IN input

(Version 1.07)

Modified to resolve the LED scroll button toggles Bluetooth and 3G when it should only toggle WiFi and REC

(Version 1.06)

Modified the device firmware to have Wifi only for the PEL 112/113 devices

(Version 1.05/1.11)

First release of the device