Poor Man's Step Voltage Testing

It is quite possible for the insulation on old motors to test OK at one voltage but fail or show signs of deterioration at higher voltages. This is the reason that step voltage testing is performed. Many Megohmmeters on the market do not have a true step voltage test function. This function is typically found on expensive Megohmmeters. You can obtain adequate results from lower cost Megohmmeters by using just two voltages. In the absence of a step voltage function, two voltages that have typically a 2:1 or 5:1 ratio, i.e. 500 and 1000 volts or 500 and 2500 volts. First test the device at the lower voltage for at least 60 seconds and plot the resistance curve. Next let the device discharge and run the test again at the higher voltage for the same period of time and plot it's resistance curve. If the resistance is lower using the higher test voltage, it is an indication that weakness or deterioration is showing up at the higher voltage which could be problematic down the road. If the values are approximately the same and increasing with time, it is a sign of healthy insulation. See the figure below for examples of both.




Figure 1 shows insulation that has signs of weakness as seen by the difference in resistance readings over time at the higher test voltage. Figure 2 show good insulation in that the resistance readings are relatively the same at both voltages over time.



©2003 Chauvin Arnoux®, Inc. d.b.a. AEMC® Instruments

Contact Us

United States & Canada:

Chauvin Arnoux®, Inc. d.b.a. AEMC® Instruments 200 Foxborough Blvd. Foxborough, MA 02035 USA (508) 698-2115 • Fax (508) 698-2118 www.aemc.com

Customer Support – for placing an order, obtaining price & delivery: customerservice@aemc.com

Sales Department – for general sales information: sales@aemc.com

Repair and Calibration Service – for information on repair & calibration, obtaining a user manual: repair@aemc.com

Technical and Product Application Support – for technical and application support: techinfo@aemc.com

Webmaster – for information regarding www.aemc.com: webmaster@aemc.com

South America, Central America, Mexico, Caribbean, Australia & New Zealand:

Chauvin Arnoux[®], Inc. d.b.a. AEMC[®] Instruments 15 Faraday Drive Dover, NH 03820 USA (978) 526-7667 • Fax (978) 526-7605 export@aemc.com www.aemc.com

All other countries:

Chauvin Arnoux SCA 190, rue Championnet 75876 Paris Cedex 18, France 33 1 44 85 45 28 • Fax 33 1 46 27 73 89 info@chauvin-arnoux.com www.chauvin-arnoux.com



Poor Man's Step Voltage Testing (pdf) 09/03